



All Crash Parts

Brisbane ☎: (07) 3865 2599 Melbourne ☎: (03) 9548 7109

Information Bulletin

Issue raised: **Ford Explorer UN Tail Lamps**

Date identified: **22/01/04**

This bulletin is to outline differences in the tail lamp for the **Explorer UN 10/96 - 10/97**, part number **FXA-21040**. On the vehicle there are two options of tail lamp, the overseas model and the Australian release model. The Australian release model does not have 2 reflectors on the tail lamp however it has a second reflector mounted to the rear bumper. Before replacing the tail lamp, ensure the replacement lamp has the same reflector setup as the vehicle. It may be necessary to replace them as a pair. See diagram below.

Note: Part **FXA-21040** has the twin reflector design as per the picture below.

